

(3)

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- I

(To be filled by the Head of School/ Institute)

1. Name of the School : SUNRISE GLOBAL SCHOOL
2. Location : PLOT NO. 4, WARD 9/A, BHARATNAGAR, GANDHIDHAM
3. Plot Area : 7463.50 Sq. Mtr
4. Plinth Area : 3923.5 Sq. mtr
5. Number of Storey's : 5F + 1
6. Year of Construction of Building : 2011
7. If the building has been constructed under the supervision
Of the qualified Engineer, the following details may be given
 - a) Name of the Engineer with qualification : RAVI TANDON
 - b) Address of Engineer : Plot no-95 office no 314 sc
Gandhidham
 - c) Set of Structural drawings used in the construction, if available : → all ready Given
 - d) Name & address of Architect with qualification : Diploma Civil Engr
8. Whether the building has been constructed for the purpose
 - a) School : YES/ NO
 - b) Residential Purpose and converted for use as a School : YES/ NO
9. Materials used for roofs
 - a) R.C.C. Slabs R.B.C. Slabs : YES/ NO
 - b) R.S. Joist & Battens : YES/ NO
 - c) Wooden joists & Battens : YES/ NO
10. Materials used for walls
 - a) Mud Mortar : YES/ NO
 - b) Cement Mortar : YES/ NO
 - c) Lime Mortar : YES/ NO
11. Flooring
 - a) Conglomerate : YES/ NO
 - b) Terrazo : YES/ NO
 - c) Brick Paving. : YES/ NO
12. A detailed drawing indicating dimensions of the rooms
Alongwith size and location of doors and windows
(Attached)



Signature with Stamp of the seal
Of the School/Institution.



PART-II
(To be filled by the S.D.E.)

No. 5869-22

a) I have visited the above mentioned school on dated 24th April And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.

b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.

c) In case the building is affected by flood, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.

d) This building can be safely occupied for normal use upto (indicate upto which it can be used)
Two Years

Sub Divisional Engineer,

Ravi Tandon

R. S. TANDON
GDA REGISTERED ENGINEER
VIC No. - 108

J.R. ASSOCIATES
GDA LIC No. 108
314, 2nd Floor, E.R. RAVI TANDON
Plot No. 95, Sector 8,
Above Birla Sunlife,
Tagore Road, Gandhidham

